

ÜRO///Parts



HEAVY-DUTY ALUMINUM THERMOSTAT HOUSING

2742000115PRM | ÜRO-020292 | 2015-2020 Mercedes M274

OEM DESIGN FAULT

Modern all-plastic thermostat housings are prone to catastrophic failure after thermal cycling and exposure to oil or transmission fluid vapor. The embrittled plastic eventually ruptures, resulting in a major leak and dangerous overheating.

ÜRO PREMIUM SOLUTION

This ÜRO Premium thermostat has been upgraded with a heavy-duty aluminum housing for a truly robust repair, which is impervious to underhood heat. This metal upgrade fixes the problem right the first time, and is covered by a lifetime warranty.

