

# ÜRO//Parts



## HEAVY-DUTY ALUMINUM THERMOSTAT W/ SENSOR

2742003400PRM | ÜRO-020293 | 2015-2020 Mercedes

### OEM DESIGN FAULT

Modern plastic thermostat assemblies are prone to catastrophic failure after thermal cycling and exposure to oil or transmission fluid vapor. The embrittled plastic housing eventually ruptures, resulting in a major leak and dangerous overheating.

### ÜRO PREMIUM SOLUTION

ÜRO has developed a thermostat with a heavy-duty aluminum housing for a truly robust repair, which is impervious to heat and underhood chemicals. This all-metal upgrade fixes the problem right the first time, and is covered by a lifetime warranty.

