

UNIQUE, INTELLIGENT, REPAIR SOLUTIONS FOR EUROPEAN VEHICLES

OE Replacement Parts

Quality replacement parts that meet or exceed OEM specifications.




Alternative to "Genuine Only"

Often the exclusive aftermarket alternative to expensive "Genuine" components.



ÜRO Classic

Accurate reproduction parts for classic vehicles, including items no longer available from the dealer.



ÜRO Premium

Problem-solving upgraded components that are superior to OEM in design and/or materials.




UNIQUE, INTELLIGENT, REPAIR SOLUTIONS



Intake Manifold Repair Kits

Replace torn rubber diaphragms and broken plastic linkages with silicone, aluminum and Delrin.
Mercedes V6 / V8, Audi / VW 4.2L



Engine & Transmission Pans

Modern pans are often plastic with integrated filters. ÜRO offers aluminum with replaceable filters.
2002-2018 BMW / Audi / VW



Pulleys w/ Name Brand Bearings

Bearings are usually the first to fail in a pulley assembly. ÜRO uses high-quality NTN/NSK bearings.
Many Popular Makes & Models



Shifter Lever Repair Kits

Replace broken plastic shifter parts with metal instead of replacing the entire automatic shifter assembly.
Jaguar & Mercedes



Collapsible Water Transfer Pipes

Replace a failed timing cover coolant seal without major engine tear down, reducing labor by 70%.
2002-2014 BMW V8 / V12



Aluminum Water Pump Pulleys

Heat-fatigued plastic pulleys can spontaneously self-destruct. Metal pulleys can take the heat - forever.
1991-2010 BMW



Trunk Latch Repair Kits

Upgrade snapped plastic actuator lever to aluminum instead of replacing the bracket assembly.
1999-2005 VW Bora / Jetta Mk4



Brake Booster Plunger Seals

Replace a single seal to eliminate whistling or hissing vacuum leaks, for a fraction of new booster cost.
1998-2015 Mercedes & Volvo



Brass Actuator Gears

Stripped teeth on plastic OE gears can disable transfer case, sunroof, or convertible top actuator motors.
BMW, Mercedes, Porsche



Metal Thermostat Housings

Tired of replacing warped or cracked plastic t-stat housings? ÜRO eliminated the problem.
BMW, Jaguar, Mini, SAAB




Valve Covers

ÜRO offers top-quality aftermarket alternatives to expensive OEM covers for many makes & models.
BMW, Audi / VW, Mini, Porsche



Thermostat Housing Nipples

Instead of replacing the entire thermostat when the plastic elbow snaps, repair it with a metal nipple.
2002-2005 Volvo V6



Intake Valley Pans

Failing RTV gaskets can escape the OE pan's flat flange. ÜRO pan has a retention lip & Viton gasket.
1993-2005 BMW M62 V8




Coolant Hose Repair Kits & Pipes

Repair pipe-hose assemblies with silicone hose and replace cracked plastic tubes with aluminum pipes.
1998-2014 BMW



Coolant Transfer Pipes

Eliminate the failure-prone plastic Audi / VW "crack pipe" with ÜRO's bulletproof alloy aluminum pipe.
2001-2009 Audi / VW V6



Mini Cooling Fan Resistors

OE resistor is exposed and fails when weathered. ÜRO resistor is well-protected by a plastic shield.
2003-2008 Mini Cooper