

STEP 1

If you have a 2009-2011 Audi A4, 2010-2011 A5/A5 Cabriolet, or 2011 Q5 with 2.0L TFSI EA888 engine, identify the correct oil separator valve for your car per Audi **TSB 17 13 43 2027731/5**.



STEP 2

Verify that Audi part number on your original oil separator valve matches the new valve part number, or cross-references correctly.

STEP 3

Using VAS Tester, check your engine control unit software version per **TSB 17 13 43 2027731/5**.

STEP 4

If vehicle has one of the following software versions and has not been updated per the **TSB**, install early-version *black* valve **06H103495AH** (06H103495E, 06H103495A, 06H103495AC):

8K2 907 115 A	8K2 907 115 J	8K2 907 115 T
8K2 907 115 AA	8K2 907 115 K	8R0 907 115
8K2 907 115 AD	8K2 907 115 L	8R0 907 115 A
8K2 907 115 B	8K2 907 115 M	8R0 907 115 B
8K2 907 115 C	8K2 907 115 N	8R0 907 115 C
8K2 907 115 D	8K2 907 115 P	8R0 907 115 D
8K2 907 115 F	8K2 907 115 Q	8R0 907 115 H
8K2 907 115 H	8K2 907 115 R	8R0 907 115 K
8R0 907 115 J	8K2 907 115 S	

STEP 5

If vehicle has one of the following software versions and has been updated per **TSB 17 13 43 2027731/5**, install updated-version *white* valve **06H103495AK** (06H103495AE, 06H103495J):

8K2 907 115 AK	8K2 907 115 AL	8R0 907 115 M
8K2 907 115 AE	8K2 907 115 AM	8R0 907 115 P
8K2 907 115 AF	8R0 907 115 AA	8R0 907 115 Q
8K2 907 115 AG	8R0 907 115 AB	8R0 907 115 R
8K2 907 115 AH	8R0 907 115 AC	8R0 907 115 T
8K2 907 115 AJ	8R0 907 115 AD	



Installation by a professional technician is recommended. Refer to the factory repair manual for vehicle-specific service procedures for this part. Tighten all hardware to factory torque specifications and observe all repair manual cautions and warnings. Use safety stands whenever beneath a vehicle and always wear protective eyewear.