


## Porsche Convertible Top Motor Gear Repair Kit

Part# 911 624 056 03K



### OEM Design

The convertible lock down motors used on the classic Porsche 964 / 993 models have brass internal drive gears, which fail over time. This renders the motor and the top inoperable, and has previously required a complete new top motor assembly, which is exorbitantly expensive.



### Problems

- Brass gear teeth become worn and break off, jamming the steel worm gear
- Attempting to operate jammed mechanism will break the worm gear shaft



### ÜRO Solution

ÜRO Parts has engineered a repair solution, which includes a replacement gear set and step-by-step instructions providing a simple and economical alternative to replacing the complete and very costly top locking motor assemblies. The kit fits both left and right motors.



### Advantages

- Repairs the convertible top motor instead of replacing the entire assembly
- Precision-machined gears ensure smooth motor operation

### Vehicle Applications

1987 - 1994 Porsche 911 Convertible