

Autotecnica



HEAVY-DUTY ALUMINUM COOLANT BYPASS PIPE

RM0720519PRM | 2014–2019 Jeep, Ram

OEM DESIGN FAULT

Plastic coolant pipes are prone to catastrophic failure after repeated thermal cycles and exposure to motor oil, grease, or transmission fluid. The embrittled plastic eventually ruptures, resulting in a major leak and dangerous overheating.

AUTOTECNICA PREMIUM SOLUTION

Autotecnica Premium has developed an aluminum coolant pipe for a truly robust repair, which is impervious to engine heat, motor oil and ATF. The sturdy all-metal replacement fixes the problem right the first time, and is covered by a lifetime warranty.

