




VW Trunk Latch Actuator Bracket Repair Kit

Part# 1J5 827 567 A-PRM



OEM Design

The trunk release actuator found in the VW Jetta MK4 is known for breaking the thin plastic relay lever, which disables the latch release mechanism. Repair typically requires replacement of the entire actuator bracket assembly, which is no more durable than the original failure-prone assembly.



Problems

- Actuator usage breaks the plastic relay lever, especially during cold weather
- Replacement of OE bracket assembly is a costly yet temporary repair, and doesn't resolve the fragile relay lever issue



ÜRO Solution

ÜRO Parts redesigned the plastic actuator relay lever using metal for vastly improved reliability. The ÜRO lever is made of sturdy aluminum and reinforced with structural ribs, making the ÜRO lever exponentially stronger than OE. Now you can permanently repair the actuator bracket instead of replacing it!



Advantages

- Improved design corrects OE deficiencies
- ÜRO relay lever is simple to install
- Aluminum construction is impervious to summer heat and winter cold
- Lifetime warranty

Vehicle Applications

1999-2005 Volkswagen Bora and Jetta MK4